



Service Bulletin

PRELIMINARY INFORMATION

Subject: Transmission Fluid Level Indicator Handle Broken

Models: 2007-2013 Cadillac Escalade Models
2007-2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe
2007-2013 GMC Sierra, Yukon Models
Equipped with Automatic Transmission RPOs MYD, MYC

Condition/Concern



Some customers may comment that while attempting to remove the transmission fluid level indicator to check the fluid, the handle breaks off. Further investigation reveals that the metal indicator material was corroded and broke where the plastic handle is attached.

Recommendation/Instructions

Technicians should replace the transmission fluid level indicator with the updated part number. The new part is darker in color as shown below.



Parts Information

| Part Number | Description |
|-------------|----------------------------|
| 24267668 | INDICATOR, TRANS FLUID LVL |

Warranty Information

For vehicles repaired under warranty, use:

| Labor Operation | Description | Labor Time |
|-----------------|--|------------|
| K9562* | Replace Transmission Fluid Level Indicator | 0.2 hr |

*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from this information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION