

Measure no.

US 52033506-01

Subject

Instrument panel snap-lock couplings are missing (2 x)

Status date (mm/dd/yy)

8/22/12

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

8/22/12

Created by

Peter Loertzing

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K19

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/ 8/6/12

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

Complaint

On some vehicles, the snap-lock couplings (rubber grommet) are missing

(Electronic parts catalogue, item 7, plate 46_1409).

Note: The designations in the electronic parts catalogue is also incorrect

(item 7 and item 4 have been switched)

Cause

Incorrect assembly at the assembly line.

Error in the electronic parts catalogue.

Measure

If the snap-lock couplings are not fitted, they can be ordered using part number: 46 63 7 691 016.

As of production 08/07/2012, the factory has been installing these parts.

The next edition of the electronic parts catalogue is expected to be adjusted accordingly.

Cause**Fault location**

62/21 Instrument cover

Fault type**Fault place****Repair Task****Special Clearance**

No

Area**Fault code**

Progman / DIS / ISTA / ISTA/P

System

State

Version
