

Measure no.

US 53056144-01

Subject

Malfunction in trip odometer(s)

Status date (mm/dd/yy)

12/6/12

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

12/6/12

Created by

Martin Bumba

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K18 K19

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

The trip odometer(s) 1 and/or trip 2 sporadically does/do not move or reset(s) to "0".

Cause

Unknown.

Measure

The topic is being investigated. For each concern, please create a PuMA case.

Answer the following questions:

- Was the anti-theft alarm system armed when switching off the vehicle?
- Did you/the customer wait for the pre-drive check after Ignition ON, or was it interrupted by engine start-up?

Describe the situation in as much detail as possible to avoid the need for queries.

Cause**Fault location**

62/11 Trip distance recorder

Fault type

Display fault

Fault place**Repair Task****Special Clearance**

No

Area**Fault code**

Progman / DIS / ISTA / ISTA/P

System

State

Version
