Tech Tips




TT 24-11-04 Date: August 26, 2011

2009-<mark>2013</mark> Routan – Powertrain Control Module (PCM) Adaptation

November 23, 2012: Update to information.


For any concerns regarding adaptation of the PCM, make sure the StarMOBILE diagnostic tool is updated to the latest level (currently 10.04.15) and use the following screens to perform the adaptation.

If StarMOBILE diagnostic tool requires software update, file can be downloaded from a link in document VSS-12-02, available on ServiceNet under Workshop Equipment> StarMOBILE Diagnostic Tool> Service Information.









































Page 5 of 21












Page 6 of 21










































Page 11 of 21












































































EXIT OUT OF STARMOBILE AND RE-OPEN IT





