

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: October 22, 2012
TO: Mitsubishi Motors Parts Managers
Mitsubishi Motors Service Managers
RE: Outlander Sport TPMS Sensor - Temporary Production
TIN NO. TIN-12-42A-001

AFFECTED VEHICLES: Certain 2013 Outlander Sport

PURPOSE

Due to a supply issue with the “snap-in” type Tire Pressure Monitoring System (TPMS) sensor, subject vehicles are temporarily being built using the 2012 “clamp in” type sensor. This change will affect approximately 6 weeks of production, or until the supply issue is resolved. An owner’s manual addendum card reflecting this change has been placed in the glove box of affected vehicles.

The TPMS sensor type can be easily identified by the valve stem.



This change is effective with the following vehicles:

- 18” alloy wheels: DE007466 built 10/18/2012
- 16” alloy wheels: DE007527 built 10/17/2012
- 16” steel wheels: DE007484 built 10/18/2012

This change will be reflected in future versions of ASA-CAPS. Until then, if a replacement sensor is required, please order the correct part number shown in the photos above. To insure appearance uniformity and owner’s manual consistency, use only the sensor type originally installed on the vehicle.

There is no affect in diagnostic or registration procedures. Both sensor types use the same diagnostic trouble codes and registration steps.