



---

# SERVICE BULLETIN

---

Classification:

EL12-081

Reference:

NTB12-107

Date:

November 19, 2012

---

## 2013 ALTIMA AND PATHFINDER BATTERY DISCHARGED AFTER USING CONSULT III PLUS VI

**APPLIED VEHICLE:** 2013 Altima (L33)  
2013 Pathfinder (R52)

### SERVICE INFORMATION

After any diagnostic or reprogramming activity using the CONSULT-III plus (C-III plus) Vehicle Interface (VI), the vehicle ignition must be cycled OFF⇒ON 5 seconds⇒OFF.

- After disconnecting a VI from a vehicle, if the ignition is not cycled, there is a potential that the BCM will **not** go to “sleep” mode.
- If the BCM does not “go to sleep”, and the vehicle is not used for an extended time, the vehicle battery voltage will be drained causing a discharged battery and a no-start condition.

### IMPORTANT:

**After disconnecting the C-III plus VI, cycle the ignition:**

**OFF⇒ON for at least 5 seconds⇒OFF**

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.