

Classification:

EL12-082

Reference:

ITB12-074

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

November 19, 2012

2013 JX BATTERY DISCHARGED AFTER USING CONSULT-III PLUS VI

APPLIED VEHICLE: 2013 JX (L50)

SERVICE INFORMATION

After any diagnostic or reprogramming activity using the CONSULT-III plus (C-III plus) Vehicle Interface (VI), the vehicle ignition must be cycled OFF⇒ON 5 seconds⇒OFF.

- After disconnecting a VI from a vehicle, if the ignition is not cycled, there is a potential that the BCM will not go to “sleep” mode.
- If the BCM does not “go to sleep”, and the vehicle is not used for an extended time, the vehicle battery voltage will be drained causing a discharged battery and a no-start condition.

IMPORTANT:

After disconnecting the C-III plus VI, cycle the ignition OFF→ON for at least 5 seconds→OFF.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.