

Key cap removal .pdf

Reference SSM42832

XK / X150

Models XJ / X351

XF / X250

Title Door Lock Cylinder Cover - Fitment at PDI / Replacement.

Category Body

Last modified 07-Dec-2012 00:00:00

Symptom 112000 Latches/Locks & Security

**Issue:**

Customer may report door lock cylinder cover missing.

**Cause:**

Cylinder cover may have been incorrectly fitted at PDI or after emergency vehicle entry.

Content

**Action:**

The sequence of installing is shown on the attached doc. Please make sure that the door lock cylinder cover is pushed firmly in the sequence shown to install all 3 clips. The cover will now be securely attached to the vehicle.

Ensure correct fitment by testing with a vigorous pull.