

Special Service Message



NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 54897 - Panoramic Roof Blind Feet Breakage or Fractured

Models : X351 - XJ

Engineer Name : Campbell Andy

Last Modified : 12-10-2012 07:02:03

Category : Body

Symptom : 105000 Roof Options

Content : Issue:

Front or Rear roof blinds inoperative

Cause:

Blind feet broken or fractured.

Action:

Should any vehicle be found to require replacement of the panoramic blind feet (Workshop manual 501-17) please ensure that the latest level part is fitted, this can be identified by a new Jaguar part number (not the number on the part) and a paint mark.

Please see attached file for information on part numbers and identification of new part.

From Vin V33044 onwards latest level parts could be fitted from production.

Please note the new parts must be fitted in pairs

File : [Blind Feet.PDF](#)