

Reference SSM58877

XK / X150

Models XJ / X351

XF / X250

Title Head Lamp / Fog Lamp - Discolouration / Distortion

Category Electrical

Last modified 14-Sep-2012 00:00:00

Symptom 201000 Lighting Systems

Issue:

Discolouration and or distortion to the head lamp and or fog lamp lens.

Cause:

If headlamps or fog lamps are switched on for long periods of time during work in a dealer and body protection is on the vehicle and covering the lamps, there is a possibility that the lens may overheat.

Content In the most extreme cases this can result in the lens becoming discoloured or distorted resulting in replacement.

Action:

If during repairs the head lamp and or fog lamp is covered please ensure the lights are switched off (including AUTO) and remain off until the body protection is removed.