

symptom[1].JPG

DISPLAY2[1].JPG

Reference SSM58957

Models XJ / X351

Title Touch Screen Remote Control

Category Electrical

Last modified 14-Sep-2012 00:00:00

Symptom 207000 Entertainment Systems

Issue:

Rear Entertainment - Touch Screen Remote Control display visually poor or innoperative.

Cause:

Internal Printed circuit board (PCB) issue.

Content

Action:

If these symptoms (examples shown or similar on attachments) are experienced on a remote display pre assured VIN # V36927 please replace the remote assy.