

Reference SSM61657

XK / X150

Models XF / X250

XJ / X350

Title JTB00268 engine hard to start after hot soak - fan running

Category Driveability

Last modified 17-Dec-2012 00:00:00

Symptom 602300 Hard Start/Long Crank

Issue: After completing technical bulletin JTB00268, some customers have reported that the engine fan is running after the engine has been switched off.

Cause: JTB00268 updates the engine control module with revised software. The software lowers the engine temperature by running the fan for a longer period

Content of time after switching off the engine.

Action: After completing JTB00268 please explain to the customer that the engine fan may run for a longer period of time than they would normally experience, and this is as a result of the software download. This is expected and is normal. The fan will stop running after a short period of time.