

**Update Prior to Sale Notice UPS7412: Front
Differential Oil Leak**

20-DEC-12

No.: 6-194NAS

Section: GENERAL
INFORMATION

Market: CAN / USA

DESCRIPTION

A limited number of 2013 model year Jaguar XJ All-Wheel Drive vehicles may exhibit an oil leak may be evident from the interface between the front differential case and the engine oil pan.

AFFECTED VEHICLES

A total of 22 2013 model year Jaguar XJ All-Wheel Drive vehicles within the listed VIN range are affected.

- XJ (X351): V42261-V44710 (see attached list)

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Refer to Technical Bulletin UPS7412NAS, *Update Prior to Sale: Front Differential Oil Leak*, for detailed inspection instructions.

Those vehicles which 'fail' the inspection process must be held pending further instructions.

PARTS

No parts required

TOOLS

Refer to Workshop Manual for any required special tools

WARRANTY

△ **NOTE:** Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time. Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**K166**' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **30 June 2013** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NO.	QTY. / VALUE
K166	B	Inspect for front differential oil leak	05.10.50	0.50	-	-
K166	C	Inspect for front differential oil leak	05.10.50	0.50	-	-
		Drive in / drive out	10.10.10	0.10	-	-

Normal Warranty policies and procedures apply

UPS7412: Affected VIN List

CANADA

RETAILER CODE / NAME	VIN
4202 Jaguar Vancouver	V44620
4202 Jaguar Vancouver	V44710
4497 Jaguar Richmond	V42261
4501 Jaguar Victoria	V44613
4501 Jaguar Victoria	V44641
4506 Jaguar Edmonton	V44629
4506 Jaguar Edmonton	V44671
4508 Jaguar Kelowna	V44633
4508 Jaguar Kelowna	V44635

USA

RETAILER CODE / NAME	VIN
1049 Jaguar Jacksonville	V44034
5381 Jaguar Albany	V43955
5387 Jaguar Orlando	V44085
5390 Jaguar Austin	V43959
5398 Jaguar Greensboro	V44090
5446 Jaguar Winston Salem	V44129
5498 Jaguar Woburn	V44125
5498 Jaguar Woburn	V44177
5614 Hampton Jaguar	V44015
5670 White Plains Jaguar	V44217
5672 Autobahn Motorcars	V44078
5675 Jaguar Cleveland	V44065
5713 Jaguar of the Gulf Coast	V44040