



# Ferrari North America

## Technical Information

Date:	January 3, 2012
Bulletin #:	1973
Campaign #:	361
Supersedes:	1968
Section:	3

**Model Type:** F142 (458 Italia)  
**Model Year:** Assembly 101393 - 102258  
**Subject:** Replacing the gearbox

Please note that, due to a non-conformity found in our supplier's production process that could cause a noise condition in some instances, it is necessary to replace the aforementioned component on vehicles from Assembly No. 101393 to Assembly No. 102258.

The list of vehicles involved in the campaign can be viewed on the Modis CS site using the "Recall and Service Campaign Management" function and entering the campaign number indicated below.

After performing the update, a ROL for managing Marriage activities must be opened.

The part which must be installed is:

- Complete DCT GEARBOX Part. No. 263938 Qty 1

### Procedure

- Disconnect the battery (as described in paragraph F2.01 step 4 of the Workshop Manual).
- Remove the complete DCT gearbox (as described in paragraph C2.02 step 1 of the Workshop Manual).
- Fit the complete DCT gearbox Part. no. 263938 (as described in paragraph C2.03 step 1 of the Workshop Manual).
- Connect the battery (as described in paragraph F2.01 step 5 of the Workshop Manual).
  - Note.: Follow the procedure for restoring the self-adaptive parameters (as described in paragraph F2.01 of the Workshop Manual).



## - ATTENTION -

This upgrade **must** be done with the DEIS PC-Tester updated to the following latest software release (or subsequent releases):

- Module 0	Portal and Troubleshooting	35
- Module 1	DEIS Diagnostic software	35
- Module 2	Technical Documentation	9
- Module 3	Tools	4

Check the software number and upgrade your DEIS Tester immediately if necessary.

Before connecting to the vehicle, remember to update the VCI interface firmware:

- Power the VCI and connect it to the DEIS PC tester using the mains cable provided.
- Run the DEIS program and wait for the firmware to update.

### Service rules

The complete DCT gearbox, Part No. 263938, which is required for this upgrade, must be ordered directly by you in the quantities required from our Spare Parts Department.

## - ATTENTION -

The replaced parts must be sent by you using the special Parts Return procedures.



# Ferrari North America

## Parts Information

Quantity	Part Description	Part Number
1	Gearbox	263938

## Warranty Information

Component code	42.3.00.001
Labor operation	42.0.90.213.0 (12.3h)
Problem code	01
Cost code	23
Campaign #	361

Thank you for your co-operation.