



Countries:	UNITED STATES, MEXICO	Document ID:	IK1400017
Availability:	ISIS	Revision:	2
Major System:	REAR AXLE	Created:	4/13/2012
Current Language:	English	Last Modified:	4/30/2012
Other Languages:	Español ,	Author:	Dan Algarin
Viewed:	75		

 Hide Details

Copy Link	Copy Relative Link	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 0	Not Helpful 0
-----------	--------------------	--	---	--	---	---	---

Applies To: Workstar-Severe Service Models - Latin America Markets All models up to VIN: 672707

The transverse torque-rod tower bracket on rear axle(s) could fail under severe duty applications.

Part #	Description	Qty.
1668798C1	BRACKET, TORQUE ROD TRANSVERSE	1

An improved and stronger transverse bracket has been released to address this concern. The improved part can be quickly identified by a marking on the side of the bracket (see picture).

It is important to follow the welding instructions outlined in Navistar's Publication.

Modified/improved Bracket Identification marking (circled in yellow)

[Hide Details](#)**Feedback Information**

Viewed: 74

Helpful: 0

Not Helpful: 0

No Feedback Found

Copyright © 2012 Navistar, Inc.