

PARTS ALERT

PA12GI-02C 15-FEB-12



NAS:

US Only:

CAN Only:

ATTENTION: Parts Manager, Parts Professional

TVF100010 – Rear Propshaft Coupling – Discovery / Discovery Series II

Please be advised that a recent batch of part number **TVF100010** - Rear Propshaft Coupling - for Discovery and Discovery Series II vehicles, may have been manufactured away from specification. Those components which are found to be out of specification must **NOT** be used for vehicle repair.

Please check all stock of the above part number as follows:

1. Check box label; if Vendor/ Supplier Code is 'FA8FB', please block / quarantine / return these parts.
2. Check the actual component against photographs provided with this ALERT to further determine a 'good' or 'no good' condition.

In the event of having a 'no good' component, please return it using return code 'ZRTN 020 – Faulty Material Number'.

If you have any queries concerning this communication, please contact the Parts Technical HelpLine.

TVF100010 (1H2Z- 7123-AA)

Good Part – text moulded into one side of part

No Good Part

