



Technical Service Bulletin

SUBJECT: INSTRUMENT PANEL WARNING LIGHTS FLASH AND/OR REDUCED POWER (LIMP) MODE			No: TSB-12-54-003
			DATE: February, 2012
			MODEL: i-MiEV
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER


PURPOSE

This TSB contains important information regarding the installation of aftermarket accessories and specifically discusses unapproved devices connected to the diagnostic Data Link Connector (DLC), DLC wiring or the vehicle's CAN-BUS circuits.

AFFECTED VEHICLES

2012 i-MiEV

DETAILS



Aftermarket devices can interfere with CAN-BUS communication and may cause intermittent flashing or illumination of the instrument panel warning lights, multiple DTCs, and possible drivability concerns. These devices include, but are not limited to the following:

- Devices that include remote diagnostics
- Data loggers
- GPS vehicle tracking devices
- Other devices that have not been approved by Mitsubishi Motors.



When installing Authorized Mitsubishi Accessories on a Mitsubishi vehicle, carefully follow the included instructions to ensure proper wiring connections and component installation.

!! IMPORTANT !!

Be advised that Mitsubishi Motors will not indemnify its dealers for any liabilities arising from the installation of non-approved accessories or equipment. Be further advised that vehicle safety features may be compromised by the installation of non-approved aftermarket accessories or equipment.

WARRANTY INFORMATION

This bulletin provides information only. **The Mitsubishi New Vehicle Limited Warranty does not apply to any aftermarket product.**