



Body

Product Service Bulletin

MODEL: HDX

SUBJECT: MUD FLAP AND DPF CONTACT, BRACKET INSTALLATION

DATE: JANUARY 13, 2012

INDEX: 13

ACTIVE PERIOD: 1/13/2012 - 1/12/2013

EXPIRES: 1/13/2013

BULLETIN: 40

PAGE: 1 OF 2

This service bulletin will add a bracket to limit the swing of the driver's side mud flap, preventing possible contact with the DPF while the unit is in transit.

Target Units: EPA 2010 HDX with ISB or ISC engines built through 10/24/11 (Body ID prior to 1131425) may be affected by this failure.

1. Turn the ignition key to the "Off" position and chock tires.
2. Install part number TBB 42000442, Tailpipe Extension Bracket, behind the driver side mud flap use existing hardware. (reference Mud Flap installation drawing 169259)
3. Remove tire chocks.

MATERIALS REQUIRED:

<u>PART NUMBER</u>	<u>QTY.</u>	<u>DESCRIPTION</u>
TBB 42000442	1	TAILPIPE EXTENSION BRACKET

WARRANTY COVERAGE:

THIS PROCEDURE IS WARRANTABLE ONLY IF THE DESCRIBED CONDITION EXISTS ON A TARGET UNIT AND THE REPAIR IS PERFORMED WITHIN THE APPLICABLE BASE WARRANTY, EXTENDED COVERAGE WARRANTY, OR ACTIVE PSB PERIOD. IF A FAILURE IS NOT FOUND, THIS PROCEDURE IS CONSIDERED PREVENTIVE AND WARRANTY DOES NOT APPLY. CLAIMS MUST BE SUBMITTED AND RECEIVED WITHIN THE ACTIVE PERIOD.

ELECTRONIC WARRANTY CODE: 7236

SRT CODE: 55-17, **TIME ALLOWANCE** - 0.3 HR.

QC: ENG

