

**SB-10043721-7590**

A PACCAR COMPANY

## Technical Information Bulletin

---

**E046**

### Section

Lube

### Subject

PACCAR MX Engines Oil Filter Cap Locks Campaign

### Release Date

1/24/2012

### Revision

01/25/12; The Warranty section has been changed. The original program included warranty payment for repair during the Basic Vehicle Warranty period or to 12/31/12. The update allows for warranty payment regardless of time, mileage.

### Condition

Kenworth has developed an improved oil filter cap lock system and campaign E046 replaces original style cap lock system.

### Chassis Affected

Identified T660s, T700s, T800s and W900s built between 05/20/09 – 11/15/11 and equipped with original style cap lock system. The attached list includes chassis with original style cap locks installed at the Kenworth factory and chassis with cap locks installed by dealers as part of an E026R campaign repair (identified from warranty claims filed). Chassis with no cap lock system installed at all, are being updated so that future repairs in that chassis will use the updated cap lock system described in the Procedure section of this bulletin.

See the attached chassis list and customer letter.

## Action

If a customer comes into your dealership with the condition described, replace the oil filter lock p. This campaign can be performed at any time convenient for the customer, for example during a scheduled mai campaign time or mileage limits (Warranty section).

## Warranty

There is no time or mileage limits for this program. Kenworth will pay parts plus dealer mark up and 0.3 hours described. Use Quick Claim E046.

Failure Location: 045-010-010  
Failure Type: 240  
SRT Code: 045-XXX

Work Accomplished: 35  
Responsibility Code: 01  
Claim Type: A

## Parts

Parts are available from PACCAR Parts.

Quantity	Part Number	Description
1	STD1534PE	Cap Screw Cap Lock Kit
1	shop materials	engine oil spillage and cleaner (\$6.00)

## Procedure

Inspect to identify whether repairs are necessary.

- For chassis with the aluminum lock device, part number 1871869PE, replace part per E046 Procedure.pdf
- For chassis that already have new style lock device, kit number STD1534PE, no repair is necessary.
- For chassis that have no locking device at all, repair per Recall bulletin E026R (DealerNet, Warranty tab, item, Federal Recall Information).



Aluminum lock: 1871869PE  
complete E046 campaign



New lock: STD1534PE  
no repair necessary



No locking  
complete E

---

## Attachments

 [E046 Chassis and Dealer-Customer Lists.xls](#)

 [E046 Procedure.pdf](#)

 [E046-E050 customer letter.pdf](#)

---

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this site are the proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Any use or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. PACCAR's system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification and may result in legal action.

© Copyright 2012 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact our [Webmaster](#).