

<b>Title</b>	Not possible to lock/unlock the car with KIR	<b>Status</b>	Released
<b>Ref No</b>	US23170.5.0 en-US	<b>Status Date</b>	2012-04-27
<b>Issuer</b>	-	<b>Issue Date</b>	2012-04-27
<b>Partner</b>	3 US 7510 Volvo Cars North America	<b>Reference</b>	
<b>Func Group</b>	3662		
<b>Func Desc</b>	burglar alarm equipment		

**Attachment**

**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
275							2011-2013		0568001-0644713	201020-201215

**CSC** Customer Symptom Codes

Code	Description
UH	Locking/unlocking/Central locking does not work
VZ	Locking/unlocking/Other central locking problems
XI	Remote control/Does not work

**DTC** Diagnostic Trouble Codes

**Text**

*This document supercedes the previous one dated 2011-01-06. Changes to this document are: TJ header updated with chassis end limits.*

*If using a printed copy of this journal, always check for the latest online version.*

**DESCRIPTION:**

The customer may experience difficulties with locking or unlocking the vehicle with the KIR (Key Integrated Remote). A previous disturbance in the supplier process may cause the battery connections inside the KIR to loose contact with the battery.

**PRODUCT MODIFICATION:**

New remotes have been introduced into production from structure week 201215.

**SERVICE:**

Replace the faulty remote.

**VOLVO STANDARD TIME GUIDE OPERATION NUMBER:**

36635-2 Remote control ignition key replace. Incl software download. SEE vstg