

<b>Title</b>	Headlamp, abnormal moisture/water leakage	<b>Status</b>	Released
<b>Ref No</b>	US25705.3.0 en-US	<b>Status</b>	2012-
<b>Issuer</b>	-	<b>Date</b>	05-17
<b>Partner</b>	3 US 7510 Volvo Cars North America	<b>Issue</b>	2012-
<b>Func Group</b>	3521	<b>Date</b>	04-11
<b>Func Desc</b>	headlamp, complete	<b>Reference</b>	VIDA

**Attachment**

File Name	File Size
TJ 25705.pdf	0.0603 MB

**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
134							2011-2012		0000194-0011012	201020-201139

**CSC** Customer Symptom Codes

Code	Description
W4	Headlights/Moisture/mist on inside of lens

**DTC** Diagnostic Trouble Codes

**Text**

**CSC = Customer Symptom Code**

**DTC = Diagnostic Trouble Code**

**Note! If using a printed copy of this Technical Journal, first check for the latest online version.**

**DESCRIPTION:** The headlamp may have abnormal moisture/water leakage at the inside of the headlamp lens. Possibly caused by a bad sealing.

**This can happen on both the Halogen and the Active gas discharge headlamps.**

Do not attempt to dry out headlight.

Pictures in attachment show the amount of water that can be on the inside of the lens.

**SERVICE:** Replace headlight unit as per VIDA.

**VOLVO STANDARD TIMES GUIDE (VSTG) INFO:**

Operation number \*35203-2\* - \*\*Headlamp assembly one side\*\* - "See VSTG "  
- Claims may be submitted under the new car warranty when there is a documented customer complaint using claim type: 01

