



Date	Group	No.	Release	Page
5.12	381	792	01	1(1)

Instrument Cluster Reprogramming

CXU

SB-10044339-9410

PI0792, Instrument Cluster Reprogramming

(May 2012)

On certain Mack Trucks built between 8/15/2011 to 5/11/2012, the icon for the mDRIVE transmission is missing in the driver information display (DID). This issue is due to the vehicles being loaded with the wrong main software. To check and correct the instrument cluster reprogramming complete the following procedure.

Repair

- 1 Perform the accessory kit number 85135025 through PTT / Vcads Pro.
- 2 Reprogram the MID 140 Instrument Cluster.
- 3 Verify mDRIVE icon is visible in the DID / Instrument Cluster after programming is complete.

Reimbursement

This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.	
Claim Type (used only when uploading from the Dealer Bus. Sys.)	B
Recall Status	
Vehicle inspected, repair not required	1- Inspected OK
Vehicle repaired per instruction	2- Modified per instruction
Labor Code	
Primary Labor Code (includes inspection and take charge)	7311H-ZP-96 0.5 hours
Causal Part	21788127
Authorization Number	PI0792
Expiration Date	22-MAY-13