

SB-10045281-4411

SI B07 01 12
Coding and Programming

July 2012
Technical Service

SUBJECT

ActiveE: Coding of the Trans Parking Lock

MODEL

E82E

SITUATION

After EME, transmission or parking lock actuator replacement, the parking lock adaption has to be relearned (via the Service Functions of ISTA ActiveE).

The parking lock coding procedure (adaption learning) fails with the current version of ISTA ActiveE.

CORRECTION

To set adaption for the parking lock, follow the attached workaround procedure.

Correction for this coding problem will be available with the next release of the ISTA ActiveE.

WARRANTY INFORMATION

Not applicable.

ATTACHMENTS

view PDF attachment [B070112 Attachment](#).

[Copyright © 2012 BMW of North America, LLC]