

SB-10046580-4089**Countries:****Availability:****Major System:** ELECTRICAL
SYSTEM**Current
Language:** English**Other
Languages:** NONE**Viewed:** 72**Document
ID:**

IK0800389

Revision: 0**Created:** 8/27/2012**Last
Modified:** 9/19/2012**Author:** Eddie
Panozzo[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 5	 0

Title: Steering harness rub possibly causing cruise to randomly drop out**Applies To:** Prostar**DESCRIPTION**

Steering column harness rub may cause cruise wires from switches to momentarily short out turning off cruise.

SYMPTOMS

- Driver complains about cruise control randomly dropping off requiring a reset.

POSSIBLE DIAGNOSTIC TROUBLE CODES

None

SIGNALS TO WATCH

Cruise status signals in DLB when problem occurs.

TROUBLESHOOTING

1. Remove steering column covers to view area in figure 1. If harness has rubbed through points indicated in figure 2 replace.



Figure 1




Figure 2.

RESOLUTION

Replace harness

 Hide Details

Feedback Information

Viewed: 71

Helpful: 5

Not Helpful: 0

No Feedback Found

Copyright © 2012 Navistar, Inc.