

SB-10046580-8799

Countries:	CANADA, UNITED STATES	Document ID:	IK0800389
Availability:	ISIS, Fleet!SIS	Revision:	2
Major System:	ELECTRICAL SYSTEM	Created:	8/27/2012
Current Language:	English	Last Modified:	10/24/2012
Other Languages:	NONE	Author:	Eddie Panozzo
Viewed:	479		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 19	 0

Title: Steering harness rub possibly causing cruise to randomly drop out**Applies To: Prostar**

DESCRIPTION

Steering column harness rub may cause cruise wires from switches to momentarily short out turning off cruise.

SYMPTOMS

- Driver complains about cruise control randomly dropping off requiring a reset.

TROUBLESHOOTING

1. Remove steering column covers to view area in figure 1. If harness has rubbed through points indicated in figure 2 replace.





Figure 1




Figure 2.

 Hide Details

Feedback Information

Viewed: 478

Helpful: 19

Not Helpful: 0

No Feedback Found

Copyright © 2012 Navistar, Inc.