



Technical Service Bulletin

96 False warning by lane change assistant (Audi Side Assist)

96 12 42 2030583/1 September 5, 2012.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2013	All	Audi Side Assist
A5	2013		

Condition

Customer complains that Audi Side Assist is providing false warnings (no vehicle is present). Concern may or may not be duplicated.

No DTCs are present in the Audi Side Assist system.

Technical Background

This condition can be created due to an incorrect hardware and software set created by the supplier.

Production Solution

A production solution is in development.

Service

A service solution is in development and no repair is available at this time.

1. Do not perform any repairs. Any repairs for this concern may be denied.
2. Instruct the customer that this condition is known, and a solution is under development. This TSB will be updated when a repair solution becomes available.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.