



# Service Bulletin

File in Section: -

Bulletin No.: PIP5067

Date: October, 2012

## PRELIMINARY INFORMATION

**Subject:** P0300 Random Misfires on Random Cylinder

**Models:** 2001-2013 Chevrolet Corvette

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A vehicle may come in with a customer concern of a SES lamp and misfire.

It may have P0301-P0308 or P0300 only

### Recommendation/Instructions

If you run into this concern and normal misfire diagnosis does not isolate the concern.

Before engine disassemble we should Inspect the torque tube coupling for damage.





2916200

## Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
F1300	Driveline Support	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.