



# Service Bulletin

File in Section: -

Bulletin No.: PIC5751

Date: October, 2012

## PRELIMINARY INFORMATION

**Subject:** Service Park Brake Message C0558

**Models:** 2013 Chevrolet Malibu

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer or technician may indicate there is a Service Park Brake Message displayed. The technician may indicate the following DTC's are set C0558 sym5A and/or C0558 sym55. The park brake may not release or cannot perform park brake calibration in GDS2.

### Recommendation/Instructions

Please check that G401 is secure and there is no paint or tape affecting contact. See picture below left rear wheel house.



2915786

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.