

Position light LED nonfunctional

Themen-Nummer	LI82.10-P-054609
Version	1
Konstruktionsgruppe	82.10 Exterior lights
Stand	09-07-2012
Gültigkeit	211### #B up to 100720 (11/2006 production)
Änderungsgrund	Damage code adjusted
Sperrgrund	

Beanstandung:

Standing light/position light nonfunctional.

Ursache:

Solder bridge between + and - of connecting line and/or cable at solder point broken.

Abhilfe:

Replacement of the headlamp.

Symptome

Overall vehicle / Lighting / Exterior lights / Standing/parking lights / Standing lights / Nonfunctional

Overall vehicle / Lighting / Exterior lights / Standing/parking lights / Parking lights / Nonfunctional

Teile

Teilenummer	ES1	ES2	Bezeichnung	Menge/Anzahl	Hinweis	EPC	Fremdteil
A 211 820 54 61			Lighting Unit - Right with Bi-Xenon & Cornering Illumination	1		X	
A 211 820 53 61			Lighting Unit - Left with Bi-Xenon & Cornering Illumination	1		X	
A 211 820 34 61			Lighting Unit - Right	1		X	
A 211 820 33 61			Lighting Unit - Left	1		X	

Arbeitswerte

Arb.-Nr.	Arbeitstext	Zeit	Schadenschlüssel	Hinweis
82-4790	REPLACE LEFT FRONT LAMP UNIT		82B01 73	
82-4800	REPLACE RIGHT FRONT LAMP UNIT		82P01 73	

Gültigkeit		
Fahrzeug	Motor	Getriebe
211.004	*	*
211.006	*	*
211.007	*	*
211.008	*	*
211.016	*	*
211.020	*	*
211.022	*	*
211.023	*	*
211.026	*	*
211.028	*	*
211.029	*	*
211.041	*	*
211.042	*	*
211.052	*	*
211.054	*	*
211.056	*	*
211.061	*	*
211.065	*	*
211.070	*	*
211.072	*	*
211.076	*	*
211.077	*	*
211.080	*	*
211.082	*	*
211.083	*	*
211.084	*	*
211.087	*	*
211.089	*	*
211.090	*	*
211.092	*	*
211.206	*	*
211.207	*	*
211.208	*	*
211.216	*	*
211.220	*	*
211.222	*	*
211.223	*	*
211.226	*	*
211.241	*	*
211.242	*	*

211.252	*	*
211.254	*	*
211.256	*	*
211.261	*	*
211.265	*	*
211.270	*	*
211.272	*	*
211.276	*	*
211.277	*	*
211.280	*	*
211.282	*	*
211.283	*	*
211.284	*	*
211.287	*	*
211.289	*	*
211.290	*	*
211.292	*	*
211.606	*	*
211.608	*	*
211.616	*	*
211.620	*	*