



SB-0024 Fuel Minder Signal Wire

Bulletin Number:	SB-0024	Revision:	NR	EIC Number:	N/A	Std. Repair Time:	N/A
Application:	Orion VII EPA10, NYCT 1375						
<u>Classification:</u>							
Information Letter	☒	Parts Bulletin	☐	Recall Letter	☐		
Service Manual Update	☐	Operator's Manual Update	☐				

NOTE: For more information, please contact the Orion Service Line at 1-800-71-ORION (1-800-716-7466).

1.0 INTRODUCTION

This Service Information Letter is to inform about the fuel minder system on NYCT 1375 buses.

The fuel minder equipment is currently disconnected on the NYCT 1375 fleet. An electrical harness was installed on the buses and connected to the I/O system.

Electrical noise can on occasion cause a false signal that the fuel filter is clogged. DBNA techs are removing the signal wire at the I/O module when a bus exhibits this code.

The fuel minder equipment will be installed on the 90 buses in an upcoming campaign.