

SB-10049339-2764

SI B71 02 12
Tools and Accessories (Engine-Chassis)

October 2012
Technical Service

PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS.

BMW centers must ensure recalls are completed after having been notified by BMW of North America, LLC (BMWNA) that a safety-related defect or noncompliance exists in any motor vehicle or item of replacement equipment in the center's possession at the time of notification. In BMW NA's case, this notification would typically be made by the issuance of a recall notification in the form of a Service Information bulletin (SIB) or transmission of a Dealer Communication System (DCS) recall message.

Under the National Traffic and Motor Vehicle Safety Act of 1966, as amended, if a recall campaign is announced by BMW NA, centers must ensure that all recalls on new vehicles and new items of replacement equipment are completed BEFORE delivery to the consumer. This means that centers may not legally deliver new motor vehicles or new items of replacement equipment to consumers with an open recall.

The Safety Act also prohibits centers from selling or leasing the motor vehicle or item of replacement equipment, unless and until the open recall has been completed BEFORE delivery. This also pertains to vehicles in the Certified Pre-Owned program, and to items of replacement equipment.

Finally, BMW centers should not sell or use parts that have been recalled by BMW NA. Please follow the specific instructions provided by BMW NA on the return or disposition of the parts.

SUBJECT

Voluntary Emissions Recall Campaign 12E-A03: Replace Emissions Label

MODEL

E70 with the M57Y engine produced from 7/2012 to 9/2012

SITUATION

Certain vehicles were produced with an incorrect model year label installed under the hood (model year 2013). This label needs to be removed and the correct model year 2012 label installed in its place.

Customers will receive notification letters informing them to make a service appointment at their BMW centers to have the correct label installed.

AFFECTED VEHICLES

This Emissions Recall Campaign involves MY 2012 E70 vehicles with the M57Y engine produced from July 2012 to September 2012.

In order to determine whether a specific vehicle has had this Emissions Recall Campaign completed or is affected by this Emissions Recall Campaign, first check if the "Emissions Recall Campaign Completed" label SD 92-435 is attached to the right (passenger) rear side of the hood in the engine compartment, close to the windshield. If the label is found, the campaign has already been performed. If

the "Emissions Recall Campaign Completed" label is not present, it will be necessary to utilize the "Service Menu" of DCSnet (Dealer Communication System) or the Key Reader. Based on the response of the system, either proceed with the corrective action or take no further action.


PROCEDURE

1. Open the engine compartment hood. The label is located on the driver's side on the underside of the hood, close to the cowl/windshield.
2. Remove the incorrect label.
3. Clean the underhood surface with a suitable cleaning solution.
4. Affix the correct MY 12 emissions label.

PARTS INFORMATION

Part Number	Description	Quantity
71 22 8 517 186	Diesel MY 12 US Emissions label	1

LABEL INSTRUCTIONS



The illustration shows a rectangular label with a black border. At the top left is the BMW logo. To its right, the text "EMISSIONS RECALL CAMPAIGN COMPLETED" is printed in bold. Below this, there are three horizontal input fields labeled "RECALL", "CAMPAIGN NO.", and "DEALER CODE NO.". At the bottom left, it says "BMW of North America, LLC Woodcliff Lake, N.J. 07677". At the bottom right, there is a small box containing "SD 92-435". Below the entire label frame, the code "GRUSB1212-01" is printed.

After the vehicle has been checked and corrected, obtain a label (SD 92-435) and with the indelible marker provided, legibly print the Recall name, Recall number, and dealer code (5 digits) on the Recall Completion Label (see illustration).

Note: Additional labels can be ordered online at BMW TIS.

Vehicle Emission Recall - Proof of Correction				
License Number	Make	Year Model	Body Type	Vehicle Identification Number
Manufacturer			Recall Number	
The above described vehicle has been repaired, modified and/or equipped with new emission control devices to meet applicable California Emission Control Laws.				
Dealer's Name		Address, City, State and Zip		
Date	Dealership's Authorized Signature			
Return this certificate to DMV <u>only</u> when required - otherwise retain for your records.				SD92-084

S12 96 U31

For California centers only: It is required by the California Code of Regulations that an executed orange "Vehicle Emission Recall - Proof of Correction" certificate (SD92-084, see illustration) be provided to each customer (for vehicles registered in the state of California), once the Recall on his or her vehicle has been completed.

WARRANTY INFORMATION

The repair described in this bulletin is covered under warranty regardless of time or mileage.

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

Defect Code: **00 71 86 01 00**

A. Before delivery to the customer (including center vehicles that are in-service)

Labor Operation:	Labor Allowance:	Description:
00 60 178	Refer to KSD2	Replace emissions label

Labor operation code 00 60 990 is a Plus labor operation.

or

B. After delivery to the customer

Labor Operation:	Labor Allowance:	Description:
00 60 178	Refer to KSD2	Replace emissions label

Labor operation code 00 60 178 is a Main labor operation.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance. Enter the Chassis Number, which consists of the last 7 digits of the Vehicle Identification Number (VIN). Click on the "Search" button, and then enter the applicable flat rate labor operation in the FR code field.

[Copyright © 2012 BMW of North America, LLC]