



Internal notification for: G_0000152945 12222B - Service Update - Inventory Vehicles Only - Incorrect Material Used for Transmission O-Ring - Revised
gm_gmmsg_q01

12/03/2012 11:35 AM

2 attachments



12222B bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 12/03/2012 Ref. number: Service / Field Action / G_0000152945
Subject: 12222B - Service Update - Inventory Vehicles Only - Incorrect Material Used for Transmission
t: O-Ring - Revised

GM CUSTOMER CARE AND AFTERSALES
DCS2862
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 3, 2012
Subject: 12222B - Service Update - Inventory Vehicles Only
Incorrect Material Used for Transmission O-Ring
Revised Part Information Section
Models: 2012-2013 Buick Regal; 2013 Buick LaCrosse and Chevrolet Malibu
Equipped with 6-Speed Hybrid Automatic Transmission (MHH)
To: All Buick and Chevrolet Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The Part Information section in bulletin 12222B has been revised to include transmission fluid. Please discard all copies of bulletin 12222A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12222B bulletin.pdf Acrobat PDF (434.7KB)
12222B bulletin

Contact
name:

Department: Service - Brand Quality
t:

Phone: