

Internal notification for: G_0000151197 12257B - Service Update - Navigation System Does Not Calculate Most Optimal Route - Revised

gm_gmssg_q01

11/14/2012 02:21 PM

2 attachments

POF

12257B bulletin.pdf GM Style Sheet.css

Your email client does not support HTML messages

Date:11/14/2012Ref. number:Service / Field Action / G_0000151197Subject:12257B - Service Update - Navigation System Does Not Calculate Most Optimal Route - Revised

GM CUSTOMER CARE AND AFTERSALES DCS2854 URGENT - DISTRIBUTE IMMEDIATELY

Date: November 14, 2012

Subject: 12257B - Service Update Navigation System Does Not Calculate Most Optimal Route Revised Service Procedure

Models: 2013 Cadillac ATS, SRX, XTS Equipped with Navigation System (IO6/UY4)

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

The service procedure in bulletin 12257B has been revised to include an additional MAP part number in Steps 2 and 7. Please discard all copies of bulletin 12257A.

END OF MESSAGE GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s): 12257B bulletin.pdf Acrobat PDF (191.0KB) 12257B bulletin

Contact name:		E-Mail:
	Service - Brand Quality	Phone:
l.		

Intended General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, roles: Service Advisor, Service Manager, Warranty Administrator