

# Technical Service Bulletin



## 94 - Dimmer cap missing from headlight switch

94 12 93 2031378/1 October 25, 2012.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6/A7	2012-2013	All	Not Applicable

## Condition

Cap on dimmer (light switch) has fallen off and cannot be found.



*Figure 1. Dimmer knob on main light switch*

## Technical Background

Not Applicable

## Production Solution

Not Applicable

## Service

Replace missing cap. Do *not* replace the main light switch. Switches replaced for this condition will be charged back.

# Technical Service Bulletin



## Warranty

<b>Claim Type:</b>	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
<b>Service Number:</b>	9405		
<b>Damage Code:</b>	0010		
<b>Labor Operations:</b>	Replace Dimmer cap	9405 1999	10 TU
<b>Diagnostic Time:</b>	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer' s discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
<b>Claim Comment:</b>	As per TSB #2031378/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Required Parts and Tools

Part Number	Part Description	Quantity
4G0 941 158 B	Cap for dimmer switch	1

## Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.