

TECHNICAL BULLETIN

LTB00473NAS1
06 SEP 2012



SECTION: 501-12

Upper Glove Box Lid Discolored

AFFECTED VEHICLE RANGE:

Range Rover Sport (LS)

VIN: AA212147 - BA299999;
BA700000 - CA725000

Model Year: 2010 - 2012

CONDITION SUMMARY:

Situation: The upper glove box lid (Ivory-color only) may be discolored or not match the center console Ivory trim.

Cause: This may be caused by an incorrect manufacturing process.

Action: In the event of a customer concern of the above, refer to the Repair Procedure outlined below to replace the upper glove box lid.

PARTS:

LR021496..... Glove box lid - Ivory - LHD

Qty: 1

TOOLS:

Refer to Workshop Manual for any required special tools

WARRANTY:

△ **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Glove box – Renew – Includes adjustment	76.46.46	2.60	81	LR021496

Normal Warranty policies and procedures apply

REPAIR PROCEDURE

RELACE UPPER GLOVE BOX LID

1. Refer to Workshop Manual section 501-12 and replace the upper glove box lid.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.