Audi

Technical Service Bulletin

72 Audi Q5 rattle from left rear seat back

72 12 03 2030729/1 September 5, 2012.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi Q5	2010 - 2012	BA000001 – CA129013	Not Applicable

Condition

Customer may report rattle sounds coming from the left rear seatback frame, near the pivot point (Figure 1).



Figure 1. Left rear seat noise area marked with red arrows.

Technical Background

The rattle sound can be caused from the torsion bar within the rear backrest pivot assembly. This portion of the seat frame is not serviceable. A production solution is in development to correct this.

Production Solution

Not applicable.

Service

No repair is available at this time.

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. Instruct the customer that this condition is known, and a solution is under development.

© 2012 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2012 Audi of America, Inc.

Page 2 of 2

all rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.