



Service Bulletin

File in Section: -

Bulletin No.: PIC5762

Date: October, 2012

PRELIMINARY INFORMATION

Subject: DTC C056D Set In Steering Wheel Angle Sensor

Models: 2013 Cadillac ATS

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

In rare instances, a technician may notice a DTC C056D set in the Steering Wheel Angle Sensor (SAS) even though the vehicle was in for repair for something unrelated to this component.

Recommendation/Instructions

Important: Do not replace the SAS until further diagnosis is performed.

A condition exists in which the SAS may falsely set a C056D whenever DTCs are retrieved from the vehicle.

- If the vehicle is in for service(s) unrelated to the SAS and its operation, the DTC should be ignored.
- If the vehicle is in for service(s) related to the SAS and its operation, follow published diagnostic procedures and repair/replace as necessary.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.