



Service Bulletin

File in Section: -

Bulletin No.: PIC5749

Date: October, 2012

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Vehicle Not Equipped With CD Player

Models: 2013 Chevrolet Camaro
Equipped with Chevrolet MyLink Radio (RPO UHQ or UP9)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customer may comment that there is no slot to insert a CD into the radio.

Recommendation/Instructions

The MyLink radio in the 2013 Camaro is NOT equipped with a CD slot in the radio faceplate and will not play CD's. If the Integrated Center Stack (ICS) is removed, you will see a slot in the radio where a CD could be inserted, however, the CD player is not operational and there are currently no plans to make it operational.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.