

# Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Touareg	2011-2012	3.0L TDI (CATA)	All	All	All

## Condition

28 12 04 December 14, 2012 2031972

**Diagnostic Trouble Code P13E6 Glow Plug Pressure Sensor Fault Stored in ECM**

DTC	Description
P13E6	Sensor or internal pressure of cylinders Implausible signal

## Technical Background

Guided Fault Finding (GFF) repair instruction for fault code P13E6 is incorrect. New instruction will be implemented into GFF.

## Production Solution

Not required

## Service



### Note:

**If the vehicle has an upcoming state emissions test and this is the only fault present, do not clear this fault, as it will clear the readiness setting from the vehicle. Many state emissions programs require readiness to be set. The readiness may be difficult to set depending on driving conditions. If you are operating in GFF, you may choose to disconnect the diagnostic connector before exiting GFF, as exiting GFF will clear all fault memories and the readiness.**

Fault code P13E6 may be found when reading out the ECM fault memory. **DO NOT** replace the Pressure Sensing Glow Plugs for this fault.

This fault will not illuminate the check engine light or cause any drivability issues.

Perform diagnosis of any other faults and return the vehicle to the customer.



# Technical Bulletin

---

## Warranty

Information only.

## Required Parts and Tools

No special parts required.

No special tools required

## Additional Information

**All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.**