



Service Bulletin

File in Section: -

Bulletin No.: PIP5040A

Date: September, 2012

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: Tech 2 Software Update Now Available to Restore Missing ST and LT Fuel Trim Parameters

Models: 2012 Buick Enclave
2012 Cadillac CTS
2012 Chevrolet Impala, Traverse
2012 GMC Acadia
with 3.0L Engine (RPO LFW)
or 3.6L Engine (RPO LFX or LLT)

This PI was superseded to update recommended field. Please discard PIP5040.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern:

Some technicians may notice that the following parameters are missing from the Engine Data List and Fuel Trim Data List when Tech 2 software version 32.005 or earlier is installed:

Short Term FT Bank 1

Short Term FT Bank 2

Long Term FT Bank 1

Long Term FT Bank 2

This is the result of a Tech 2 software concern and it has been corrected in software version 32.006.

Recommendation/Instructions:

If this concern is encountered, update your Tech 2 with the latest software to view these parameters.

ADDITIONAL SI KEYWORDS:

P0171 P0172 P0174 P0175 P1174 P1175

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.