



Service Bulletin

File in Section: -

Bulletin No.: PIP5061

Date: September, 2012

PRELIMINARY INFORMATION

Subject: Possible No Start With Low Or No Compression Noise CEL On

Models: 2013 Chevrolet Spark
Equipped with 1.2L LLO

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern:

You may encounter a customer concern of No start, CEL, or engine noise with low or no compression with no obvious cause.

Recommendation/Instructions:

Record actual compression readings.

If Low or no compression is validated, then remove the Camshaft cover and inspect for a broken or dislodged Camshaft Actuator Spring. If found, contact TAC for further recommendations.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.