

© 2012 Mazda Motor of America, Inc.

Subject: BRAKE FLUID SPILLAGE CAUTION	Bulletin No: 04-004/12
	Last Issued: 10/18/2012


APPLICABLE MODEL(S)/VINS

2007-2012 CX-7

DESCRIPTION

Use extreme care when replacing or re-filling brake fluid at the master cylinder. There are several wiring harnesses that run under the master cylinder that can be easily spilled upon.

CAUTION: Brake fluid contains properties that can cause a short-circuit in a wiring harness. If brake fluid is spilled on any wiring harness, clean it up immediately using a shop rag and water. Be sure to wipe the fluid completely from the harness.



NOTE: Any vehicle repair and/or parts replacement due to brake fluid spillage will not be covered under the manufacturer's warranty coverage.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.