

© 2012 Mazda Motor of America, Inc.

Subject: CRUISE MAIN INDICATOR LIGHT (AMBER) OCCASSIONALLY COMES ON	Bulletin No: 09-039/12
	Last Issued: 10/18/2012

APPLICABLE MODEL(S)/VINS


2010-2011 Mazda3

2010-2012 CX-7

DESCRIPTION

Some vehicles may experience an occasional and unexpected illumination of the cruise main indicator light (amber) with the ignition key operation cycle of OFF-START-ON. It can be cancelled by the operation of either auto cruise switch or the ignition key operation cycle of OFF-START-ON.

NOTE: The normal operation of the cruise control is not affected by this issue.



This problem may be caused by a weak battery (low voltage) and replacement of the battery is recommended to correct it. Use the GR8-1291 to test the battery.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.