

Subject:

UNUSUAL RATTLE / BUZZ TYPE NOISE FROM PRESILENCER

Bulletin No: 01-026/12

Last Issued: 11/20/2012

APPLICABLE MODEL(S)/VINS

2010-2013 CX-9 vehicles with VINs from JM3 TB ***** 200001 to JM3 TB ***** 400869 (produced from July 28, 2009 to October 15, 2012)


DESCRIPTION

Some vehicles may exhibit an unusual rattle/buzzing type noise from the presilencer when driving at approximately 1800 rpm.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the presilencer (A). Refer to MS3 online or Workshop Manual (section 01-15 EXHAUST SYSTEM REMOVAL/INSTALLATION [MZI-3.7]).



3. Verify repair.

Bulletin No: 01-026/12 © 2012 Mazda Motor of America, Inc.	Last Issued: 11/20/2012
--	--------------------------------

PART(S) INFORMATION

Part Number	Description	Qty.
CA11-40-300B	Presilencer	1
AJ17-40-305	Gasket	1
FSB8-40-305	Gasket	2

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	82
Damage Code	9B
Part Number Main Cause	CA11-40-300B
Quantity	1
Operation Number / Labor Hours:	XXH7FXRX / 0.5 Hrs.