

<b>Subject:</b>  <b>MIL ILLUMINATION WITH DTC P2096:00</b>	<b>Bulletin No:</b> 01-027/12
	<b>Last Issued:</b> 12/14/2012

## APPLICABLE MODEL(S)/VINS

2010-2012 CX-7 2.3L turbo vehicles with VINs lower than JM3ER\*\*\*\*\*424994 (produced before April 26, 2012)

## DESCRIPTION

Some vehicles may exhibit a MIL illumination with DTC P2096:00 stored in memory.

The PCM logic control has been changed to eliminate this concern.

Customers having this concern should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE

1. Verify the customer complaint of a MIL illumination with DTC P2096:00 stored in memory.
2. Perform a Warranty Vehicle Inquiry using the eMDCS system:
  - If the PCM has not already been reprogrammed according to TSB 01-020/12, "MAZDA SERVICE PROGRAM (MSP36) - NONCONFORMITY TO EVAPORATIVE EMISSION STANDARD" issued on June 15, 2012, reprogram it now. NOTE: TSB 01-020/12 contains the program files needed for DTC P2096:00.
  - If the PCM has already been reprogrammed according to TSB 01-020/12, "MAZDA SERVICE PROGRAM (MSP36) - NONCONFORMITY TO EVAPORATIVE EMISSION STANDARD" and DTC P2096:00 remains stored in memory, refer to the MS3 online instructions or Workshop Manual for further troubleshooting information.
3. Verify repair.

## WARRANTY INFORMATION

Use the warranty information in TSB 01-020/12, "MAZDA SERVICE PROGRAM (MSP36) - NONCONFORMITY TO EVAPORATIVE EMISSION STANDARD" for warranty claim submission.