

Reference	SSM58077
Models	LR4 / L319 Range Rover Sport / L320
Title	Air Suspension Valve Block replacement 10MY onwards
Category	Chassis
Last modified	13-Jul-2012 00:00:00
Symptom	304000 Suspension System
Content	<p><b>Issue:</b> Land Rover are currently evaluating reports where diagnosis has led to a concern with the Air Suspension Valve Block on Discovery 4/ Range Rover Sport 10My onwards.</p> <p><b>Cause:</b> Currently under investigation.</p> <p><b>Action:</b> If a customer has reported a concern with the Air Suspension and upon diagnosis it appears to be an issue related to the Air Suspension Valve block, please submit an ePQR. If your dealership is within a 100 mile radius of Solihull, contact the Engineer below so that we can then arrange a dealership visit at reasonably short notice to view the concern and help with diagnosis of the issue.</p> <p>Richard Attwood: 0121 700 8729.</p>