

**CSC-10052249-6885**

May 31, 2013

SUBJECT: FIELD REPAIR 413-9  
Models 579 and 567 Exterior Lights Self-Test Switch  
EXPIRATION DATE: May 31, 2014

CUSTOMER NAME  
CUSTOMER ADDRESS  
CITY, STATE ZIP

Dear Peterbilt Customer:

Peterbilt Motors has decided that certain Model 567/579 vehicles built between January 23, 2012 and April 15, 2013 were manufactured with incorrect or disabled programming for the exterior light self-test switch. Additionally, Safety Recall 213-B disabled the software parameter, removed the switch and installed a switch plug.


The software has now been updated to enable the parameters for the exterior light self-test switch to function properly. This letter is to inform you that the vehicle(s) represented by the VIN number(s) in this letter are eligible for this Field Repair.

<b><i>The problem is...</i></b>	Disabled software parameter and switch plug
<b><i>What your dealer will do...</i></b>	Enable the software parameter and install the light switch
<b><i>What you must do ...</i></b>	Contact your Peterbilt Dealer to schedule an appointment for repair

Please contact your nearest Peterbilt Dealer to schedule this repair. This repair should take less than 0.5 hours, and will be performed at no cost to you.

We regret any inconvenience this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood  
Director Customer Service