

**CSC-10052549-6595**

June 04, 2013

SUBJECT: FIELD REPAIR 413-1  
Cummins EPA 2013 Aftertreatment Fuse Rating  
EXPIRATION DATE: June 04, 2014

CUSTOMER NAME  
CUSTOMER ADDRESS  
CITY, STATE ZIP

Dear Peterbilt Customer:


Peterbilt Motors has decided that all Conventional Model and Model 320 vehicles built with Cummins 2013 EPA engines before February 21, 2013 were manufactured with incorrectly sized fuses powering the after-treatment system. The installed fuse is rated at 5 Amps, and should have been 10 Amp. These vehicles may experience a loss of power to after-treatment components due to inadequate fuse rating. This letter is to inform you that the vehicle(s) represented by the VIN number(s) in this letter are eligible for this Field Repair.

<b><i>The problem is...</i></b>	5 Amp fuse installed for the aftertreatment system
<b><i>What your dealer will do...</i></b>	Install a 10 Amp fuse for the aftertreatment system
<b><i>What you must do ...</i></b>	Contact your Peterbilt Dealer to schedule an appointment for repair

Please contact your nearest Peterbilt Dealer to schedule this repair. This repair should take about 30 minutes, and will be performed at no cost to you.

We regret any inconvenience this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood  
Director Customer Service