



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

CSC-10053943-7613

August 2014

RE: 2014 Odyssey

Dear Honda Odyssey Owner:

What is the reason for this notice?

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. On some 2014 Odyssey vehicles, the Odyssey emblem was incorrectly installed on the passenger's side of the rear tailgate. The emblem should be installed on the driver's side of the rear tailgate. American Honda Motor Company highly recommends that you participate in this Product Update. The placement of the emblem may indicate that the vehicle has had repairs performed that are consistent with it being involved in a crash. This could affect the resale value of the vehicle.

What should you do?

Please contact any authorized Honda dealer to have the Odyssey emblem removed from the passenger's side and a new one applied to the driver's side of the rear tailgate. This work will be done *free of charge*.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact American Honda's customer service at 800-999-1009 and select option 4. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this product update may cause you.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

Agosto del 2014

RE: Odyssey 2014

Estimado propietario de un vehículo Honda Odyssey:

¿Cuál es el motivo de esta notificación?

Nuestros registros indican que no se ha completado una ACTUALIZACIÓN DE PRODUCTO en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. En algunos vehículos Odyssey 2014, el emblema de la Odyssey fue instalado incorrectamente en el lado del pasajero de la puerta eléctrica trasera. El emblema debe ser instalado en el lado del conductor de la puerta eléctrica trasera. American Honda Motor Company recomienda altamente que usted participe en esta Actualización de producto. La colocación del emblema puede indicar que al vehículo se han realizado reparaciones que son consistentes con que éste ha estado involucrado en un choque. Esto podría afectar el valor de reventa del vehículo.

¿Qué debe hacer?

Por favor comuníquese con cualquier concesionario Honda autorizado para retirar el emblema de la Odyssey del lado del pasajero y aplicar uno nuevo en el lado del conductor de la puerta eléctrica trasera. Este trabajo se realizará *sin costo alguno*.

Si tiene preguntas

Si tiene preguntas acerca de este aviso o necesita asistencia para ubicar un concesionario, comuníquese con Servicio al Cliente de Honda al 800-999-1009 y seleccione la opción 4. Usted también puede encontrar esta información en www.Hondacars.com.

Le pedimos disculpas por cualquier inconveniente que pueda haberle causado esta actualización de producto.

Atentamente,

**American Honda Motor Co., Inc.
División Automotriz de Honda**

AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BO LETÍN DE SERVICIO #13-063 JB3