

September 10, 2013

SUBJECT: Field Repair 713-1
Model 579 RH U/C After-Treatment Harness
EXPIRATION DATE: September 10, 2014
Affected VINs are shown on the opposite side of this page

*Customer Name
Customer Address
Customer City, State Zip*

Dear Peterbilt Customer:


Peterbilt Motors has decided that certain model 579 vehicles built between November 5, 2012 and July 15, 2013 were manufactured with aerodynamic closeouts that have incorrect cutout locations for the after treatment harness. This issue may result in the after treatment harness becoming frayed or damaged. This letter is to inform you that the vehicle(s) represented by the VIN number(s) in this letter are eligible for this Field Repair.

<i>The problem is...</i>	Incorrect cutout locations for the after-treatment harness in the aerodynamic closeouts
<i>What your dealer will do...</i>	Modify the closeouts and inspect harness for any damage
<i>What you must do ...</i>	Contact your Peterbilt Dealer to schedule an appointment for repair

Please contact your nearest Peterbilt Dealer to schedule this repair. This repair should take less than 0.5 hours, and will be performed at no cost to you.

We regret any inconvenience this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Director Customer Service